
CHRIST CHURCH CATHEDRAL, CHURCH HALL AND VICARAGE



Anglican Church of Christ
Lydiard St - Film 1 / Frame 41
- Ballarat Conservation Study,
1978



Christ Church Hall

Location

49, AND 49A LYDIARD STREET SOUTH, BALLARAT CENTRAL - PROPERTY NUMBERS 2048187, 2020960, BALLARAT CITY

Municipality

BALLARAT CITY

Level of significance

Incl in HO area indiv sig

Heritage Overlay Numbers

HO50

Heritage Listing

Ballarat City

Statement of Significance

Last updated on - March 5, 2024

What is significant?

How is it significant?

Why is it significant?

Part of Recommended Area A1.1.

No SoS provided in this citation. Please refer to the Attachments section in this place record for further information.

Heritage Study/Consultant	Ballarat - Ballarat Heritage Precincts Study, Dr David Rowe and Wendy Jacobs, 2006; Ballarat - Ballarat Conservation Study, Jacobs Lewis Vines Architects, 1978; Ballarat - Pilot Study. Standardised Heritage Assessment Methodology, Landmark Heritage, David Helms Heritage Planning & History Making, 2024;
Construction dates	1854, 1857, 1867, 1868, 1920,
Architect/Designer	Caselli, Henry R, Richards, P.S. (Percy), Backhouse & Reynolds, James, Edward,
Hermes Number	177352
Property Number	

Physical Description 1

Church

The church is of a simple early English Gothic composition with five imposing lancet light windows to the west elevation. Simple stepped bluestone buttresses separate paired lancet windows on the side elevation. Basalt coping stones, supported, on corbel blocks define the steep gable roof, and are terminated by simple crosses.

The effect of this church is drastically altered by the new porch, which destroys the proportion of the west elevation. There was originally a simple entrance portico. However this building provides a contributory streetscape component, and appears to be in good condition.

Church Hall

This simple double gabled brick hall was constructed in 1868. It is a simple early English Gothic structure with paired lancet windows with hood moulds and simple stepped buttresses. The stone dressings have been painted. The hall is in good condition with an intact slate roof (the finials have been removed) and unpainted brickwork. An early photo of c.1920 shows the hall with a picket fence; more appropriate than the present metal railing fence.

This place/object may be included in the Victorian Heritage Register pursuant to the Heritage Act 2017. Check the Victorian Heritage Database, selecting 'Heritage Victoria' as the place source.

For further details about Heritage Overlay places, contact the relevant local council or go to Planning Schemes Online <http://planningschemes.dpcd.vic.gov.au/>