
HOUSE & WELL AT 21 - 23 Daly Street



22476 House - 23 Daly Street, Doncaster East (1)

Location

21 - 23 Daly Street DONCASTER EAST, Manningham City

Municipality

MANNINGHAM CITY

Level of significance

Recommended for Heritage Overlay

Heritage Listing

Manningham City

Statement of Significance

Last updated on -

What is Significant?

The house, constructed in the c.1880 or earlier with later additions c.1924 and c.1930, and the brick domed well at 21-23 Daly Street, Doncaster East.

How is it Significant?

The house and well at 21-23 Daly Street, Doncaster East are of local historic significance to Manningham City.

Why is it Significant?

The house has historic significance as a now rare surviving example of an early house associated with the rural development of this area prior to suburban development in the post-war period. It is of interest for apparently containing the very altered remnants of an earlier cottage within the present house, which faces away from the street toward Wetherby Road, thus indicating its construction prior to later subdivision. It is of particular significance for the remnant brick domed well, which is now extremely rare within the municipality. (RNE criteria A.4, B.2 and D.4)

Heritage Study/Consultant Manningham - Manningham Heritage Study Review, Context Pty Ltd, 2006;

Hermes Number 22476

Property Number

Historical Australian Themes

Local Themes

7.05 - Houses of the 1920s-30s

Physical Description 1

When inspected in March 2005, this property contained a timber hipped-roof house, which appeared to have been built in stages. However, the property was subsequently destroyed by fire.

The front section appeared to date from the Inter-War period. The entrance faced the left-hand side, with a gable projecting to the right. The upper gable was half-timbered and the windows had hoods. There was a return verandah with stop-chamfered posts, which has been partially infilled with fibro-cement on the north side. Windows to the front of the house are paired timber-framed sashes with corrugated iron awnings. What appeared to be the earliest section of the house at the rear had been altered to the extent that it is difficult to understand its original form, and original details such as the windows have been replaced, making the date of its construction uncertain.

The siting of the house is of interest because the facade is at right angles to Daly Street, and the house faces East toward Wetherby Road, thus indicating its construction on a larger lot extending to Wetherby Road prior to the suburban development of this area.

The house appears to be unoccupied and is in poor condition. The garden is mature and includes a Canary Island date palm and a large pine.

A feature of the yard is an early brick domed well near the south east corner of the house. It appears to be in good condition.

Physical Conditions

Condition Poor

Integrity

Integrity Altered

Physical Description 2

Threats Deterioration

Physical Description 3

Associations

Arthur Roy Hardidge, Rupert Gedye

This place/object may be included in the Victorian Heritage Register pursuant to the Heritage Act 2017. Check the Victorian Heritage Database, selecting 'Heritage Victoria' as the place source.

For further details about Heritage Overlay places, contact the relevant local council or go to Planning Schemes Online <http://planningschemes.dpcd.vic.gov.au/>