URE FARM COMPLEX, GEMBROOK NORTH POST



Ure Farm Complex & Description of the Complex

Location

330 Ure Road GEMBROOK, Cardinia Shire

Municipality

CARDINIA SHIRE

Level of significance

Included in Heritage Overlay

Heritage Overlay Numbers

HO134

Heritage Listing

Cardinia Shire

Statement of Significance

Last updated on -

The Ure Farm Complex, (former Gembrook North PO, later Silverwells) is significant to Victoria because of its integrity to an early date of farm building construction and its planted setting. The complex provides excellent evidence of the development of the dairying industry in the area and the State and the development of early rural service centres in the shire townships.

This is one of the most complete small farm complexes in the State and is notable for the number and early date

of its various farm structures. It also contains important early examples of timber construction techniques used in farm buildings. The complex is important, too, as part of the first Gembrook village settlement. It has significant associations with the Ure family who played a major role in the development of the area.

State Significance

Silverwells residence on VHR H611; HO125 (Cardinina Shire Planning Scheme)

Heritage Cardinia - Cardinia Shire Heritage Study 1996, Graeme Butler & Cardinia - Cardinia Shire Heritage Study 1996, Graeme Butler & Cardinia - Cardinia Shire Heritage Study 1996, Graeme Butler & Cardinia - Cardinia Shire Heritage Study 1996, Graeme Butler & Cardinia - Cardinia Shire Heritage Study 1996, Graeme Butler & Cardinia Shire Heritage Study 1996, Graeme Study 1996, Graeme

Study/Consultant 1996;

Construction dates 1875,

Other Names 330 Ure Road, Gembrook,

Hermes Number 30152

Property Number

Physical Description 1

This farm complex includes a gabled weatherboarded farm house, a later fibre cement sheet clad house, and log outbuildings; many including early finishes, fittings and machinery and one including a letter slot thought to be connected with its post office function. There is a well to the north of the outbuildings, linked by a pump mechanism.

There is a massive oak is to the south of the house, the orchard to the north and large Monterey pines to the east

Physical Conditions

Many parts of the complex are in poor condition although extensive tree surgery has been carried out on the surrounding trees.

Historical Australian Themes

Historical Themes

- 3.3 Dairying
- 9.10 Post offices

11.0 Evidence of: Life style, housing and landscape choice of notable figures residing in the district

Physical Description 2

Associations - Ure, John; Ure, Robert

This place/object may be included in the Victorian Heritage Register pursuant to the Heritage Act 2017. Check the Victorian Heritage Database, selecting 'Heritage Victoria' as the place source.

| iirie <u>mup://piammigso</u> | chemes.dpcd.vic.gov | v.au/ | | |
|------------------------------|---------------------|-------|--|--|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |