

EAST DONCASTER HALL



22469 East Doncaster Hall -
1-5 Andersons Creek Road,
Doncaster East (1)



22469 East Doncaster Hall -
1-5 Andersons Creek Road,
Doncaster East (2)



22469 East Doncaster Hall -
1-5 Andersons Creek Road,
Doncaster East (3)



22469 East Doncaster Hall -
1-5 Andersons Creek Road,
Doncaster East (4)

Location

1-5 Andersons Creek Road and Cnr. Blackburn Road DONCASTER EAST, Manningham City

Municipality

MANNINGHAM CITY

Level of significance

Included in Heritage Overlay

Heritage Overlay Numbers

HO6

Heritage Listing

Manningham City

Statement of Significance

Last updated on -

Of local historical significance as an expression of community endeavour, as a place of past community focus, and possibly with continuing social value for local people.

Heritage Study/Consultant	Manningham - Manningham Heritage Study Review, Context Pty Ltd, 2006; Manningham - Doncaster & Templestowe Heritage Study Additional Historical Research, Carlotta Kellaway, 1994;
Hermes Number	22469
Property Number	

Historical Australian Themes

Local Themes

6.06 - Community halls

Physical Description 1

The hall is a primarily cavity clinker-brick building, with large sections of pressed red brick. It has a gable roof clad in corrugated Colorbond steel with the ridge running east-west. The main gable end over the front (east) entrance is cement sheet with coverboards and a timber lattice vent at the apex. (The gable end was almost certainly originally asbestos cement sheet, though it may have been replaced with more modern fibre cement sheet in the recent renovations.) Other gableends are weatherboards with a similar timber lattice vent. An articulated double gable projects from below the main ridge on the south side, and another secondary gable projects from the main roof line on the north-west corner.

On the south-west corner is a skillion-roofed brick toilet block.

Windows are four-light double sashes, the top sliding, as for a conventional double-hung sash; the bottom is a hopper. There are three buttresses on each side of the main hall (north and south facades); they are beside rather than between the windows.

The main entry is to the east in the centre of the gable end wall; there is a second door at the rear (north) of the building opening onto a brick and concrete landing.

Physical Conditions

Condition Good

Integrity

Integrity Minor Modifications

This place/object may be included in the Victorian Heritage Register pursuant to the Heritage Act 2017. Check the Victorian Heritage Database, selecting 'Heritage Victoria' as the place source.

For further details about Heritage Overlay places, contact the relevant local council or go to Planning Schemes Online <http://planningschemes.dpcd.vic.gov.au/>