

---

# MORELAND RAILWAY STATION SIGNAL BOX

---

## Location

MORELAND ROAD, COBURG, MERRI-BEK CITY

## Municipality

MERRI-BEK CITY

## Level of significance

Incl in HO area indiv sig

## Heritage Overlay Numbers

HO180

## Heritage Listing

Merri-bek City

---

## Statement of Significance

Last updated on - January 1, 2008

The Moreland signal box is of state historical and technological significance. It retains Winters double line block instruments which are now rare in signal boxes of the period outside the Upfield Line. It is historically significant because of its association with local industry through the factories and stores which owned sidings in the Moreland Station complex which were served from this signal box.

Heritage Study/Consultant	Moreland - City of Moreland Heritage Review, Allen Lovell and Associates, 1999; Moreland - City of Coburg Heritage Conservation & Streetscape Study, Timothy Hubbard Pty Ltd, 1991;
Architect/Designer	Sims, George W,
Hermes Number	59067
Property Number	

---

## Physical Description 1

The Moreland Road signal box is a simple one-and-a-half-storey building which has a red-painted gabled corrugated iron roof with scalloped bargeboards and a small finial trimming the south gable. The walls are weatherboard and the simple timber windows form a horizontal band along the south, east and north facades, allowing a view of the railway tracks. A staff toilet is attached.

Massive timber floor framing carries interlocking machinery. The chimneys and fireplaces have been removed. The signal masts, typical of many installations, are the lattice type with somersault home and fixed distant arms with cast iron finials remove. Double line block safe working instruments are still in situ.(2)

(2) Andrew Ward & Associates, Upfield Railway Heritage Study. The same signalling system on the former St Kilda Railway Line has been removed as a result of its Light Rail upgrading.

Key Architectural Elements: original corrugated iron clad roof  
carved timber bargeboards  
two storey weatherboard construction

Conservation Guidelines: replace missing six pane vertical sash windows

Comparative Examples: Signal Boxes Gardiner, Kooyong and Mentone Railway Stations

Note:

During the course of this study, works have been proposed and undertaken along the Upfield railway line. These works have included the dismantling and removal of some of the railway related structures recommended for Heritage Overlay protection in this study.

*This place/object may be included in the Victorian Heritage Register pursuant to the Heritage Act 2017. Check the Victorian Heritage Database, selecting 'Heritage Victoria' as the place source.*

*For further details about Heritage Overlay places, contact the relevant local council or go to Planning Schemes Online <http://planningschemes.dpcd.vic.gov.au/>*